

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:				
Company	Vicky S. Miller Environmental Specialist			
OSM	Christine Belka Environmental Protection Specialis			
OGM	Steve Demczak Environmental Scientist III			

Inspection Report

Permit Number:	C0070039		
Inspection Type:	COMPLETE OVERSITE		
Inspection Date:	Thursday, September 24, 2009		
Start Date/Time:	9/24/2009 7:00:00 AM		
End Date/Time:	9/24/2009 2:00:00 PM		
Last Inspection:	Wednesday, August 12, 2009		

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 70's

InspectionID Report Number: 2149

Accepted by: jhelfric

9/30/2009

Permitee: CANYON FUEL COMPANY LLC Operator: CANYON FUEL COMPANY LLC

Site: **DUGOUT CANYON MINE**

Address: PO BOX 1029, WELLINGTON UT 84542

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

	Total Permitted		
104.70	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

✓ Federal
✓ Underground

✓ State
□ Surface

□ County
□ Loadout

✓ Fee
□ Processing

☐ Processing

Types of Operations

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

□ Other

There are no pending compliance actions for the Dugout Canyon Mine permit area.

The Permittee is current relative to the required electronic quarterly water monitoring submittals for 2009.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Date

Monday, September 28, 2009

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Inspection Continuation Sheet

Inspection Type: COMPLETE OVERSITE
Inspection Date: Thursday, September 24, 2009

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	•	Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale	~		•	
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		V	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		V	
4.e	Hydrologic Balance: Effluent Limitations	V			
5.	Explosives	V			
6.	Disposal of Excess Spoil, Fills, Benches	V			
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		V	
8.	Noncoal Waste	V		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage	V			
11.	Contemporaneous Reclamation	✓			
12.	Backfilling And Grading	V			
13.	Revegetation	V			
14.	Subsidence Control	V		✓	
15.	Cessation of Operations	✓			
16.a	Roads: Construction, Maintenance, Surfacing	V			
16.b	Roads: Drainage Controls	✓		✓	
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check	✓			
20.	Air Quality Permit	✓		V	
21.	Bonding and Insurance	✓		V	
22.	Other				

Permit Number: C0070039

Inspection Type: COMPLETE OVERSITE
Inspection Date: Thursday, September 24, 2009

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

DOGM Permit will expire on March 17, 2013. This permit was renewed on October 10, 2008. The permit was signed by the Director of DOGM. The UPDES Permit will expire on Nov. 30, 2009. The SPCC plan was reviewed by a P.E. on March 14, 2008.

2. Signs and Markers

The permit sign is located at the gate to the property. Information meets the minimium requirements of the R645 Coal Rules.

3. Topsoil

The topsoil piles at the waste rock sites was inspected. There were no signs of wind or water erosion. It appears to be mostly vegetated by weeds.

4.a Hydrologic Balance: Diversions

The diversions were spot inspected and were functioning as designed. A pipe by the upper sub-station has cracked and will need repaired. The permittee has stated that they will fix or replace the pipe.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment ponds were inspected on June 30, 2009. No hazardous conditions were reported. The mine site pond did contain water but was not discharging during the inspection. I did not notice any hazardous conditions to the sediment pond during the inspection.

4.d Hydrologic Balance: Water Monitoring

Second quarter water data was submitted to the Division.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inspected with no hazardous conditions noticed during the inspection. The permittee inspected the refuse pile on August 12, 2009. The report is P.E. certified. No hazardous conditions were reported.

8. Noncoal Waste

The mine site was clear of non-coal waste material.

14. Subsidence Control

This data is in the Annual Report.

16.b Roads: Drainage Controls

The permittee has cleaned out the diversions along the road.

Inspection Continuation Sheet

Permit Number: C0070039

Inspection Type: COMPLETE OVERSITE Inspection Date: Thursday, September 24, 2009

Page 4 of 4

20. Air Quality Permit

The Air Qualitly Permit is DAQE-AN0116340009-07.

21. Bonding and Insurance

The insurance policy will expire on July 31, 2010. The accord form was reviewed and meets the requirements of the R645 Coal Rules. The bonding amount is \$3,550,000. The Reclamation Agreement was inspected and is signed by the Division. The total disturb area is 101.1 acres.